

Fall Permanent Seeding

August 15 - November 1

Lime	2 tons/ac
5-10-10 Fertilizer	1000 lbs/ac
0-20-0	500 lbs/ac
Unscarified Service Lespedeza	60 lbs/ac
Ky-31 Fescue	30 lbs/ac
Rye Grain	25 lbs/ac
★Straw Mulch	2 tons/ac

Fall Permanent Seeding - Centipede:

September 1 - February 28

Lime	2 tons/ac
Fertilizer (low nitrogen approved for Centipede)	(Appropriate fertilizer approved for centipede application)
Rye Grain	90 lbs/ac
Centipede Seed	15 lbs/ac (overseeded in spring)
★Straw Mulch	2 tons/ac

Winter Temporary Cover

November 1 - February 28

Lime	2 tons/ac
10-10-10 Fertilizer	700 lbs/ac
Oats	50 lbs/ac
Rye Grain	20 lbs/ac
★Straw Mulch	2 tons/ac

Spring Permanent Seeding

March 1 - April 30

Lime	2 tons/ac
5-10-10 Fertilizer	1000 lbs/ac
0-20-0	500 lbs/ac
Scarified Sericea Lespedeza	50 lbs/ac
Ky-31 Fescue	30 lbs/ac
Browntop Millet	20 lbs/ac
★Straw Mulch	2 tons/ac

Spring Permanent Seeding - Centipede:

April 1 - July 15

Lime	2 tons/ac
Fertilizer (low nitrogen approved for Centipede)	(Appropriate fertilizer approved for centipede application)
Centipede Seed	90 lbs/ac
★Straw Mulch	2 tons/ac

Late Spring Permanent Seeding

March 15 - June 30

Lime	2 tons/ac
10-10-10 Fertilizer	1000 lbs/ac
0-20-0	500 lbs/ac
Scarified Sericea Lespedeza	40 lbs/ac
Common Bermuda Grass (hulled)	8 lbs/ac
★Straw Mulch	2 tons/ac

Summer Temporary Cover

June 30 - August 3

Lime	2 tons/ac
10-10-10 Fertilizer	700 lbs/ac
Browntop Millet	40 lbs/ac
★Straw Mulch	2 tons/ac

NOTES:

- ★ Mulch will be doubled if crimping is the method used.



TOWN of CLAYTON

USE WITH THE TOWN of CLAYTON STANDARD SPECIFICATIONS ONLY

SEEDING SPECIFICATIONS

SCALE:
Not To Scale

DETAIL #
2 350.01

REVISION DATE:
July, 2010

SHEET #:
1 of 1